

ERT - Simulacro / ERT - Drill: Run on 12/09/2021

This document was created in MY Compliance Management on 01/12/2021 00:39:52

Audit Details

Audit name:	ERT - Simulacro / ERT - Drill
Audit date:	12/09/2021
Auditor:	Antonio Gonzalez
Audit details:	Simulacro en áreas de trabajo / Work Area Drill
Overall Outcome:	Completed
Emergencia / Emergency	Derrame de sustancia quimica peligrosa / Hazardous chemical spill
Breve descripción del evento / Brief event description	Fuga en Descarga de Cal , Reagent 383 Cal
Area / Location	Reagent
Especificar ubicación / Specify location	Reagent 383 Cal
Departamento responsable / Responsible department	Process Plant-Reagent Service
Hora de inicio / Starting Time	09:00 a.m.
Hora de finalización / Ending time	9:30 a.m.

Notes

Reagent 383 Cal, Process Plant-Reagent Service.

1. Situación: Ruptura de manguera de descarga de botella de transporte de Cal, lesionando a una trabajadora.
2. Personal de reagent activa el protocolo de emergencia (llamado, evacuación)
3. Llegada de los equipos de respuesta a emergencia el sitio, Puesto de comando, extracción de la lesionada, descontaminación y entrega a personal de clínica, descontaminación de los rescatistas.

Response Summary

Section	Completed	Not completed
Audit	1	0

Audit Criteria

#	Criteria	Details	Response
1	Completed Drill	Responsible will determine the drill	Completed

Signatures

ERT - Simulacro / ERT - Drill: Run on 12/09/2021

This document was created in MY Compliance Management on 01/12/2021 00:39:52

Capacity: Foreman, Firefighting, Safety

Name: Antonio De Jesús González Castillo



Documents



Extraccion y descontaminacion del paciente



Preparacion de equipo de intervension.



Atencion de trabajador afectado por fuga de cal.